





The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER

Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:				
Company	Vicky S. Miller Environmental Specialist			
OGM	Steve Demczak Environmental Scientist III			

Inspection Report

Permit Number:	C0070039		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, April 20, 2010		
Start Date/Time:	4/20/2010 10:00:00 AM		
End Date/Time:	4/20/2010 3:00:00 PM		
Last Inspection:	Wednesday, March 17, 2010		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 2339

Accepted by: jhelfric

5/6/2010

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: DUGOUT CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Min	eral	Own	ershi
141111	CIUI	~ ** **	CI 3111

Types of Operations

✓ Underground

9,751.00	Total Permitted
106.70	Total Disturbed
	Phase I
	Phase II
	Phase III

Current Acreages

✓ Federal

Surface

State County

Loadout

✓ Fee

Processing

☐ Other

☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions for the Dugout Canyon Mine permit area.

The Permittee is current relative to the required electronic quarterly water monitoring submittals for 2009.

Inspector's Signature:

Steve Demozak, Environmental Scientist III

Date

Wednesday, April 28, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 20, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	. []			
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	a Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 20, 2010

Page 3 of 3

2. Signs and Markers

The permit sign is located at the gate to the property. Information meets the minimium requirements of the R645 Coal Rules.

4.a Hydrologic Balance: Diversions

Diversions are in the process of clean up diversions. Several diversions have been cleaned that are located in the sun shine.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The mine site sediment pond contained water but was not discharging. No hazardous conditions were noticed during the inspection.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected with no hazardous conditions noticed.

8. Noncoal Waste

The mine site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.